

DITCH INSPECTION FORM

DITCH NAME August Kutzner Ditch

TYPE 1515

OVERALL RATING

RECONST DATE 2002

LAST EXC

5 EXCELLENT

0+00 STA 29 Carroll

LENGTH 10300'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE 25329.45

CURRENT CONDITION AND PLAN OF ACTION

| | | |
|----------------|--|--|
| SEDIMENT | <input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON | |
| BANK STABILITY | <input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED | |
| OUTLET PIPES | <input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR | |
| VEGETATION | <input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES | Downed atrees along wooded section needs hand work |
| FUTURE | 2020 | 2021 |

Ditch starts in Sec 29 Carroll TWP north of Salem Carroll road and flows north-northeast to Rusha Creek. The upper reaches are 0.05%-0.10% grade. The lower section near Rusha is backwater influenced at times and water sits for extended periods. Sediment accumulates in this area along with trash and other residue. Maintenance work currently limited to mowing and spraying. Generally mow, cattail spray, brush spray schedule. Cattail spray in 2019.

DATE INSPECTED: 3.8.2018

INSPECTED BY: Mike Gargac