

DITCH INSPECTION FORM

DITCH NAME Bolsinger Road Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1978

LAST EXC 2012

5 EXCELLENT

4 GOOD

0+00 STA 22 Salem

LENGTH 1034'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$1649.48

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE	2020 nothing planned	2021

Road ditch located on the west side of Bolsinger Road starting at Woodrich Road and flowing north towards Muddy Creek. Lower end sits with water for extended periods due to Muddy Creek backwater. No filter strips on agricultural ground. Low maintenance ditch routinely mowed by Salem TWP. Lower section reconstructed and moved over by Salem TWP to improve approach to bridge. No work planned for 2019.

DATE INSPECTED: 1.29.2018

INSPECTED BY: Mike Gargac