

# DITCH INSPECTION FORM

DITCH NAME Chas Breutkreitz Ditch

TYPE 6131

OVERALL RATING

RECONST DATE 2008

LAST EXC

5 EXCELLENT

4 GOOD

0+00 STA 36 Benton

LENGTH 7500

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$79009.04

## CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Mowed 2017
FUTURE	2020	2021

Ditch starts east of Benton Carroll Road north of Kolb Rd and south of the Norfolk and Southern RR. Ditch flows east to Benton Carroll Road then south on the west side of the road, crossing Kolb Road then south outletting into a pipe which eventually outlets into Lacarpe Creek. 0.05% grade in most of the ditch. Outlet piped section to Lacarpe is the limiting factor for grade. Ditch is subseptible to willow and cattail growth especailly on the section through the field. Spot spray for brush and or cattails if needed in 2019.

DATE INSPECTED: 3.8.2018

INSPECTED BY: Mike Gargac