

DITCH INSPECTION FORM

DITCH NAME Dehring Ditch

TYPE 6131

OVERALL RATING

RECONST DATE 2015

LAST EXC 2015

5 EXCELLENT

4 GOOD

0+00 STA 36 Benton

LENGTH

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Check seeding in some areas
FUTURE	2020	2021

Ditch starts on the west side of Benton Carroll Road on the north side of the double Norfolk and Southern RR and flows north to the outlet at a RCP. This closed portion then flows to the Toussaint. The ditch is routinely mowed by Ottawa County as part of their road maintenance. Two limited areas do not have the 10' filter strip installed. These areas were flagged, but a general letter to all landowners about the filters strip may be necessary. No major work planned for 2019.

DATE INSPECTED: 1.29.2018

INSPECTED BY: Jarred Molesky