

DITCH INSPECTION FORM

DITCH NAME Eisman Group Main

TYPE SWCD Group

OVERALL RATING

RECONST DATE

LAST EXC

5 EXCELLENT

0+00 STA 16 Benton

LENGTH 2065'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$4749.75

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS & PHRAGMITIES <input type="checkbox"/> PHRAGMITIES	
FUTURE	2020 Inspect no major work planned	2021 inspect no work planned

A group tile main located south of Trowbridge Road and starting just east of Graytown Road and flowing east-southeast to a concrete drop structure at Packer Creek west of Stange Road. The structure and outlet pipe are in good condition. Generally no major work required unless there is damage to the outlet structure or a break in the tile. No work planned for 2019.

DATE INSPECTED: 3.6.2018

INSPECTED BY: Mike Gargac