## **DITCH INSPECTION FORM**

TYPE SWCD Group

**OVERALL RATING** 

DITCH NAME Goodeman Ditch

RECONST DATE 1968		LAST EXC		5 EXCELLENT 4 GOOD
0+00 STA 10 Salem		LENGTH 5900'		☐ 3 FAIR ☑ 2 POOR ☑ 1 VERY POOR
ASSESSMENT BASE \$1231.30				
CURRENT CONDITION AND PLAN OF ACTION				
SEDIMENT	☐ GOOD CONDITION ☐BOTTOM EXCAVATION 5-10 YRS ☑ NEEDS EXCAVATION SOON			
BANK STABILITY	☐ BANKS GOOD ☐ BANKS STEEP LESS THAN 1.5:1 ☐ RIP RAP NEEDED		Lower end standing water with soft mushy banks	
OUTLET PIPES	GOOD CONDITION NEED REPAIR			
VEGETATION	☐GOOD CONTROL ☐ NEEDS MOWING ☑ BRUSH ☑ CATTAILS ☑ PHRAGMITIES		Large trees east of Gordon Rd and light brush west of Gordon Rd	
FUTURE	2020		2021	
Located between Portage River South Road and the Portage River, this ditch outlets into the Green Bayou				

Located between Portage River South Road and the Portage River, this ditch outlets into the Green Bayou approximately 1300 east of Green Bayou Drive. Approximately 700' east of Green Bayou Drive is marsh. Original design outlet elev. was 571.00 and ditch design grade varies from 0.03%-0.07%. At times backwater influence is up to or west of Gordon Road..Cattails and phragmities are a problem east of Green Bayou Drive. This area is mowed back and clear downstream as far east as equipment can work. There are larger trees and brush in two sections between Green Bayou Dr. and Gordon Rd. West of Gordon Rd is light brush. A bottom excavation is needed and will give some benefit especially west of Gordon Rd, but landowners need to install filterstrips to help prolong the usefull life. Continue to do control for brush to gain access for an excavation. Due to water levels it appears that this project will not be able to be restored to the original design elevations. Mow and or brush spray for control in 2019. This is an ongoing battle on brush and cattails.

DATE INSPECTED: 2.15.2018 INSPECTED BY: Mike Gargac