

DITCH INSPECTION FORM

DITCH NAME Freimark Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1973

LAST EXC 1992

5 EXCELLENT

4 GOOD

0+00 STA 18 Benton

LENGTH 14966'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$7302.15

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input checked="" type="checkbox"/> NEEDS EXCAVATION SOON	1.5'-2.0' avg planned for 2018-2019
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Sporadic brush, and fallen trees
FUTURE	,2020	2021

Ditch starts at east side of Nissen Rd just north of Moline Martin Road, flows east -northeast crossing Elliston Trowbridge Rd to Paker Creek the outlet. 85-90% of the ditch has good filter strips. Increased fallen trees in wooded area near Packer Creek. Survey planned for 2017 was not complete. Need to get survey and plan in 2018 for excavation in fall winter 2018 to spring 2019.

DATE INSPECTED: 4.19.2018

INSPECTED BY: Mike Gargac