

# DITCH INSPECTION FORM

DITCH NAME Jacob Younker Ditch

TYPE 6131

OVERALL RATING

RECONST DATE 1961

LAST EXC 2016

5 EXCELLENT

4 GOOD

0+00 STA 11 Allen

LENGTH 7293'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$1433.68

## CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	Completed bottom excavation 2016
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	some light cattail growth in areas
FUTURE	2020 nothing planned	2021

Narrow road ditch along the south side of Walbridge Road starting at Martin Williston Rd and flowing east to Opfer Lenz Rd then turning south along the west side to a sewer which outlets into Turtle Creek. Ditch is routinely mowed by Allen TWP. There are not any filter strips on any of the agricultural ground. Some limited excavation was done on the lower section by a landowner, approximately 500' in 2013, and another 2000' done in fall of 2014. A bottom excavation and trimming the field side ditch slopes to 1.5:1 was completed in 2016 along with a small section of road side rip rap near the upperend. Upon completion this ditch should provide decent drainage. Most tile outlets are still near the bottom. Will try to get landowners to install filter strips. No major work planned for 2019.

DATE INSPECTED: 2.15.2018

INSPECTED BY: Mike Gargac