

DITCH INSPECTION FORM

DITCH NAME Krumnow Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1969

LAST EXC 2013,2016

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA 18 Benton

LENGTH 6600'

ASSESSMENT BASE \$2115.74

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Light brush on most of ditch some cattaills on lower reach near Elliston Trow Rd
FUTURE	2020	2021

Ditch starts east of Nissen Rd and south of Trowbridge Rd, flows east, north, and northeast to Trowbridge Rd, flows east on the south side of the road, crosses Trowbridge west of Elliston Trowbridge flows north then turns east and outlets into a catchbasin and sewer on the west side of Elliston Trowbridge Rd. The outlet is a catchbasin and sewer on the west side of Elliston Trowbridge Road that flows north to Turtle Creek. Catch basin and sewer are clean in good condition with good flow. Fieldside ditch slope along Trowbridge Road was excavated to a 2:1 side slope due to bank slippage in spring of 2016. Mow or brush spary in 2019.

DATE INSPECTED: 2.15.2018

INSPECTED BY: Mike Gargac