

# DITCH INSPECTION FORM

DITCH NAME LaCarpe Creek (Gaeth)

TYPE 6131

OVERALL RATING

RECONST DATE 1990

LAST EXC 2015

5 EXCELLENT

4 GOOD

0+00 STA 32 Salem

LENGTH 19160'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$38279.01

## CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Light brush and reoccurring willows ditch was sprayed for brush and then mowed because of landowner complaints
FUTURE	2020	2021

This ditch starts east of Toussaint Portage Rd north of Christiansen Rd and flows generally east to Atwater Rd. The only real issue is that this project did not go south along Atwater Rd then east and to the RR culvert. This project requires 10' filter strips and there is some encroachment by some landowners. The ditch is on a 05% grade and 0% in some reaches. There is a long stretch of one sided construction along a woods and it takes dilligence to keep the brush from moving into the ditch and removing dead fallen ash trees. There is some sediment buildup already starting due to landowners farming operations. Normal routine maintenance is mowing or spraying for brush. Look at brush spray in 2019 especially the section from Behlman Rd to Sr 19 because of willows.

DATE INSPECTED: 3.29.2018

INSPECTED BY: Mike Gargac