

DITCH INSPECTION FORM

DITCH NAME Lau Ditch

TYPE 1515

OVERALL RATING

RECONST DATE 2015

LAST EXC

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA SEC 1 Allen

LENGTH 11235'

ASSESSMENT BASE \$154972

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE	,2020	2021

This is a half section ditch between Opfer Lentz Rd and Nissen Rd flowing south to north. Ditch starts north of Walbridge Rd just on the south side of the N&S RR and flows north on the half section line crossing SR 579 and Curtice East West Rd, then flowing east northeast to Crane Creek at the Lucas County line. This ditch is required to have a 10' wide filter strip. Some trees falling in ditch along woods section. Continue to monitor filter strip compliance. Some fallen trees along wooded sections. Needs brush spray through house lot areas to control willows especially north of Curtice E & W Rd. This ditch may require a few years of annual mowing or spraying to control persistent brush. Mow and or brush spray in 2019.

DATE INSPECTED: 3.26.2018

INSPECTED BY: Mike Gargac