

DITCH INSPECTION FORM

DITCH NAME Lenz Ditch

TYPE 1515

OVERALL RATING

RECONST DATE 1995

LAST EXC

5 EXCELLENT

0+00 STA 36 Clay

LENGTH 17100'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$78572.68

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input checked="" type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	Need to start planning on an excavation
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Light brush, cattails in sections ditch mowed in 2017
FUTURE	,2020	2021

Ditch starts on north side of Whitney Road and flows north-northeast, crossing Holts East, Nissen, Elliston Trowbridge, Oestreich, James Street, Toussaint North Road and outlets into Toussaint Creek. There is some backwater influence in the lower section. This ditch is required to have a 10' wide filter strip. In most places it is pretty good, but some landowners habitually ignore this and are encroaching on the filterstrip. Generally in good condition. This ditch is usually mowed every year by landowner request although not needed in my opinion they don't complain of the cost. Usually requires some cattail and brush spray every other year. Will most likely mow in 2019.

DATE INSPECTED: 3.26.2018

INSPECTED BY: Mike Gargac