

DITCH INSPECTION FORM

DITCH NAME Lickert Harder Rd Kolb

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1971

LAST EXC 2013

5 EXCELLENT

4 GOOD

0+00 STA 35 Benton

LENGTH 2415'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$1083.80

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input checked="" type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	mowed by Benton Twp
FUTURE	2020 nothing planned	2021 nothing planned

Located on west side of Lickert Harder Rd. with the upper end at the watershed break with the upper end of Lickert Harder Road Ditch. This ditch flows south to Lacarpe Creek Branch (Kaiser). Provides surface water drainage. Landowner near upper end has pump system to outlet subsurface drainage. Road ditch mowed by townshiop so limited work needed. Nothing planned for 2019.

DATE INSPECTED: 2.1.2018

INSPECTED BY: Mike Gargac