

# DITCH INSPECTION FORM

DITCH NAME Linker Portage Rd Pipe

TYPE 6131

OVERALL RATING

RECONST DATE 1961

LAST EXC

5 EXCELLENT

0+00 STA 20 Harris

LENGTH 2310'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$6179.56

## CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE	2020 inspection nothing planned	2021 inspection, nothing planned

Piped from south of Elmore Eastern Rd along Linker Portage Rd to Sugar Creek. Visible inspection of the pipe and catchbasins show good flow, good conditon and no sediment. The outlet into Sugar Creek is intact. Currently staff is working on the watershed and base to hold a six year review and base increase hearing. If this is complete in 2018 no major work planned for 2019.

DATE INSPECTED: 3.8.2018

INSPECTED BY: Mike Gargac