

DITCH INSPECTION FORM

DITCH NAME Lohrbach Ditch

TYPE 1515

OVERALL RATING

RECONST DATE 1997

LAST EXC

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA 34 Salem

LENGTH 8400'

ASSESSMENT BASE \$16871.30

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input checked="" type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	1.0' avg
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Mowed in 2017
FUTURE	2020	2021

Ditch starts east of Behlman Rd and south of the Conrail RR and flows east to a cutoff of Lacarpe Creek east of Atwater Rd on the south side of the Conrail RR. Aproximately 2400' of the upper reach is through a woods with one sided construction. Light brush in this area and it requires diligence to keep the brush from encroaching. This project requires 10' filter strips and farm operators need constant reminders to keep them intact. Cattail spray in 2019.

DATE INSPECTED: 1.29.2018

INSPECTED BY: Mike Gargac