

DITCH INSPECTION FORM

DITCH NAME Miller-Foss Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1969

LAST EXC

5 EXCELLENT

0+00 STA 30 Carroll

LENGTH 6500'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$1667.90

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input checked="" type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	1.0' average
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Routinly mowed by Carroll Twp some light brush on field side bank
FUTURE	2020	2021

Located on west side of Toussaint Portage Rd, starting at Salem Carroll Rd. and flowing north crossing Beir Rd to the Meyer-Klein Ditch. From Beir Rd north approx 3800' was piped by Carroll TWP. The open ditch portion is a design grade of 0.05%. It provides good drainage, but the upper 1000' appears to have more sediment than the lower section. Banks are good but there are no filter strips on this half mile section. Carroll TWP does routine mowing. No major work planned for 2019..

DATE INSPECTED: 2.1.2018

INSPECTED BY: Mike Gargac