

DITCH INSPECTION FORM

DITCH NAME George Mylander Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1980

LAST EXC

5 EXCELLENT

0+00 STA 6 Salem

LENGTH 3050'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$8162

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input checked="" type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input checked="" type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Needs some hand work along woods
FUTURE	2020	2021

This ditch starts near the middle of Sec 6 Salem TWP and flows east then south to SR 105. Access is a major issue with this project. There are no easy off road access points. You must travel through crop fields which can be an issue during the cropping season. Some issues on the outlet tile from the catchbasin to the outlet. This was an existing tile used as part of the project. There are some washouts and it appears that it will need replacement. Will probably need a replacement for the basin. Need to get survey data and plan for replacement or repair

DATE INSPECTED: 4.18.2018

INSPECTED BY: Mike Gargac