

DITCH INSPECTION FORM

DITCH NAME Opfer Lenz Rd (Valasek)

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1978

LAST EXC 2004

5 EXCELLENT

4 GOOD

0+00 STA 23 Clay

LENGTH 7078'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$7935.62

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	Generally south of the RR is more of an issue
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Reocuring Light brush north of Martin Moline
FUTURE	2020	2021

Road ditch on west side of Opfer Lenz Road starting at the north side of Hellwig Rd and flowing north crossing the Norfolk and Southern RR, Moline Martin Rd and outletting into a sewer and eventually Turtle Creek. Good flow and grade north of Moline Martin. Steeper banks on this section and thereis some bottom meandering. Stone and other debris are constant issue with the RR at the ditch culverts. Constant fight to keep mandatory filter strips. Brush spray in 2019.

DATE INSPECTED: 3.1.2018

INSPECTED BY: Mike Gargac