

DITCH INSPECTION FORM

DITCH NAME Regatta Subdivision

TYPE 6131

OVERALL RATING

RECONST DATE 2019

LAST EXC

5 EXCELLENT

0+00 STA Lot 1 Sec 4 Danbury

LENGTH 230'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE 33268.00

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE		

Everything in good working order. About 3" of sediment in the water control structure on the outlet side of the weir. Sediment should not affect system functionality but will monitor.

No work planned except inspection for 2021.

DATE INSPECTED: 4.29.2020

INSPECTED BY: D. Toris