

DITCH INSPECTION FORM

DITCH NAME Reiman Road Ditch

TYPE 6131

OVERALL RATING

RECONST DATE 1964

LAST EXC

5 EXCELLENT

0+00 STA 26 Clay

LENGTH 810'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$730.30

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input checked="" type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE	2020 nothing planned	2021 nothing planned

This is just a small shallow road ditch on the west side of Reiman Rd near Edgefield Drive. In most places 1.0'-2.0' deep. It is narrow with quite a few driveway culverts. Any future work should be included with a road upgrade. In my opinion this project receives no real benefit from the maintenance program. No work planned for 2019.

DATE INSPECTED: 3.1.2018

INSPECTED BY: Mike Gargac