## **DITCH INSPECTION FORM**

DITCH NAME Rolla Tank Ditch		TYPE SWCD Group		OVERALL RATING  ☐ 5 EXCELLENT
RECONST DATE 1978		LAST EXC 2011		☐ 3 EXCELLENT ☐ 4 GOOD ☐ 3 FAIR
0+00 STA 7 Benton		LENGTH 6527'		2 POOR 1 VERY POOR
ASSESSMENT BASE \$3525				
CURRENT CONDITION AND PLAN OF ACTION				
SEDIMENT	☐ GOOD CONDITION☐ BOTTOM EXCAVATION☐ NEEDS EXCAVATION			
BANK STABILITY	□ BANKS GOOD     □ BANKS STEEP LESS     □ RIP RAP NEEDED	THAN 1.5:1		
OUTLET PIPES	GOOD CONDITION NEED REPAIR			
VEGETATION	☐GOOD CONTROL ☐ NEEDS MOWING ☐ BRUSH ☑ CATTAILS ☐ PHRAGMITIES		Ottawa C	nowing by Benton Twp and County Some cattails in limited areas
FUTURE	2020		2021	
Road ditch along the east side of Nissen Road starting about 600' south of the N&W RR flowing north crossing the RR to Walbridge Rd then along the south side of Walbridge Rd to a pipe outlet at Elliston Trowbridge Rd. Biggest				

Road ditch along the east side of Nissen Road starting about 600' south of the N&W RR flowing north crossing the RR to Walbridge Rd then along the south side of Walbridge Rd to a pipe outlet at Elliston Trowbridge Rd. Biggest issue is the steep road grade to the RR and bank stability. The RR installed a signal base at the southeast corner of the RR and Nissen Rd. It appears that some grade was compromised for the upstream reach. The RR culvert inlet control is higher than the first culvert upstream. The ditch ws moved over along Walbridge Rd in 2011 so it is basically a new ditch on this section. The landowner along Walbridge removed some surface drain structure pipes that were rusted. Now these surface drains outlet directly into the ditch with some overfall. With a good grass filterstrip and grassed surface drain there may not be an issue. There is some minor cutting where the structure pipes were removed but after a couple of seasons it does not appear to be a problem. It will still require some periodic inspection to see if reamins OK. No major work planned for 2019.

DATE INSPECTED: 2.6.2018 INSPECTED BY: Mike Gargac