

DITCH INSPECTION FORM

DITCH NAME Roose Ditch

TYPE 1515

OVERALL RATING

RECONST DATE 1996

LAST EXC

5 EXCELLENT

0+00 STA 33 Benton

LENGTH 5863'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$12068.47

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input checked="" type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Mowed in 2017
FUTURE	2020	2021

Ditch starts just south of Sondergeld Rd and flows north, turns east along south side of True Rd for a short distance then crosses True Rd going north to the Conrail RR turns east along the south side of the RR to Stange Rd. It crosses the RR and then flow north on the west side of Stange Rd to the outlet. Good flow and grade from the RR north to the outlet. The culvert under the RR requires frequent inspection and work to remove stone which slides in from the RR bed. Main issue is cattail and phragmitie growth. Spot spray brush in 2019.

DATE INSPECTED: 2.22.2018

INSPECTED BY: Mike Gargac