

DITCH INSPECTION FORM

DITCH NAME Sandrock Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1969

LAST EXC 1997

5 EXCELLENT

4 GOOD

0+00 STA 4 allen

LENGTH 5525'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$1057.25

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input checked="" type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	Greater issue near lower end
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Mowed in 2017
FUTURE	2020	2021

This ditch starts at the north side of Walbridge Rd on the west side of the TECO right-of-way (old streetcar line) and flows north to SR 579 then turns east on the south side of SR 579 for a short distance to the outlet which is a pipe under SR 579 at Wildacre Rd. Water sits in the lower end (300') which enhances cattail growth and sedimentation. There is good access on the east side but there are not any filter strips on any of the agricultural land, which is almost a mile. Filter strips would prolong the useful life of this project but have been unsuccessful in getting landowner to install filter strips. Check for cattail and brush regrowth in 2019 and spot treat if necessary.

DATE INSPECTED: 2.27.2018

INSPECTED BY: Mike Gargac