

# DITCH INSPECTION FORM

DITCH NAME Schessler Ditch

TYPE 6131

OVERALL RATING

RECONST DATE 1960

LAST EXC 2017 partial

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA 20 Clay

LENGTH 7960'

ASSESSMENT BASE \$2708.10

## CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input checked="" type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Light brush along Reiman Rd
FUTURE	2020 nothing planned	2021 nothing planned

Road ditch on the south side of Moline Martin Rd starting just west of Billman Rd and flowing east to Reiman Rd then south along the west side of Reiman Rd crossing Elmdale Drive to the outlet which is a pipe to Turtle Creek. A bottom excavation was completed in 2017. Much of the section along Moline Martin has minimal to no grade between culverts. There is a sewage discharge issue in the area near Downing. There are numerous culverts along Moline Martin that are marginal for structural integrity. Need to inspect these often. Since major work is complete this project needs a six year review and base increase hearing. This should happen in 2018 or after the current fund is back to positive number. Spot spray brush and cattails in 2019.

DATE INSPECTED: 3.5.2018

INSPECTED BY:

Mike Gargac