

DITCH INSPECTION FORM

DITCH NAME Schultz Ditch Main

TYPE 6131

OVERALL RATING

RECONST DATE 2016

LAST EXC 2016

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA 25 Carroll

LENGTH

ASSESSMENT BASE 98,868.05

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Ditch was mowed fall 2017
FUTURE	2020	2021

Ditch starts on the east side of Toussaint South Road south of Bier road. Ditch flows east crossing Brokate Road, Carroll Erie Road then turns south south east to Fritchie Road which is the downstream limit of the project. The ditch continues south to its terminus at Lacarpe Creek. The section from Fritchie Road to Lacarpe was cleaned by the landowner on the east side of the ditch. Usually backwater is up to Carroll Erie Road. Since it is a new project there are some areas where seeding is lacking. Landowners need educated on the mandatory filter strips. May need some spot spraying for brush in areas where one sided construction was done. Check for seeding and spot spray brush if needed in 2019.

DATE INSPECTED: 2.6.2017

INSPECTED BY: Jarred Molesky, Mike Gargac