

DITCH INSPECTION FORM

DITCH NAME SR 590 (Goetz)

TYPE 6131

OVERALL RATING

RECONST DATE 1969

LAST EXC 2014

5 EXCELLENT

4 GOOD

0+00 STA 34 Benton

LENGTH 1750'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$826.86

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input checked="" type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input checked="" type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE	2020 Inspection nothing planned	2021

Road ditch on the west side of SR 590 west of Rocky Ridge. The upper end is near the intersection of Woodside Drive and SR 590, and it flows north to a sewer at the drive of the first house south of the Norfolk and Southern RR. The original project did not go any farther north to a suitable outlet. ODOT did a bottom excavation and cleaned most of the portion under maintenance except a section on the upstream end. They did go downstream of the RR which now improves the flow. There are not any filter strips on the section under maintenance so this improvement may be short lived. ODOT does routine mowing so from ditch maintenance standpoint there are very minimal costs such as Admin and inspection. Nothing planned for 2019.

DATE INSPECTED: 2.1.2018

INSPECTED BY: Mike Gargac