

DITCH INSPECTION FORM

DITCH NAME Valasek Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1970

LAST EXC 1991

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA 24 Clay

LENGTH 6110'

ASSESSMENT BASE \$1160

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input checked="" type="checkbox"/> NEEDS EXCAVATION SOON	NEXT 2-3 YEARS
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input checked="" type="checkbox"/> NEED REPAIR	multiple steel tile outlet pipe showing signs of rusting
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Small light brush and cattails Ditch was mowed fall of 2017
FUTURE	2020	2021

This ditch starts near the center of Sec 24 Clay TWP then flows east to Nissen Rd then down the west side of the road and outlets into a sewer at Hellwig Rd. The design grade is 0.05%. There no filter strips on any part of this ditch. As with most projects the lifespan and condition of a project is usually in direct proportion to how the landowners and farm operators treat the ditch. There are numerous individual tile outlets which are beginning to rust. This may be an issue in the next 5-7 years. Original schedule was to do survey work in 2018. Right now this will get pushed to 2019 with a possible excavation in fall 2019 to spring 2020.

DATE INSPECTED: 3.12.2018

INSPECTED BY: Mike Gargac