DITCH INSPECTION FORM

DITCH NAME Yauch Ditch		TYPE 6131		OVERALL RATING ☐ 5 EXCELLENT
RECONST DATE 1964		LAST EXC 2017		☐ 3 EXCELLENT ☐ 4 GOOD ☐ 3 FAIR
0+00 STA 21 Salem		LENGTH 14850'		2 POOR 1 VERY POOR
ASSESSMENT BASE \$2983.87				
CURRENT CONDITION AND PLAN OF ACTION				
SEDIMENT	☐ GOOD CONDITION ☐ BOTTOM EXCAVATION 5-10 YRS ☐ NEEDS EXCAVATION SOON		Excavated spring 2017	
BANK STABILITY	☐ BANKS GOOD ☐ BANKS STEEP LESS THAN 1.5:1 ☐ RIP RAP NEEDED		Most slopes reexcavated to 1.5:1 and bottom width to 3'	
OUTLET PIPES	GOOD CONDITION NEED REPAIR			
VEGETATION	☐GOOD CONTROL ☐ NEEDS MOWING ☐ BRUSH ☐ CATTAILS ☐ PHRAGMITIES		Needs some spot seeding in areas on ditch banks	
FUTURE	2020 brush spray		2021	
This ditch outlets into the I	ittle Portage just west of Muc	Idy Crook North Pood	It is back	wester influenced and water

This ditch outlets into the Little Portage just west of Muddy Creek North Road. It is backwater influenced and water sits for extended periods, up to and west of Mud Creek Road. This causes rapid sedimentation. Although the outlet is in marsh, from there up to Mud Creek Road has good access and CRP areas. West of Mud Creek Road no filter strips, over the edge farming and furrow drainage. Since thi sproject was recently excavated and put back to the original plan specs it needs at a six year review and base increase. Mow or brush spray in 2019.

DATE INSPECTED: 3.6.2018 INSPECTED BY: Mike Gargac