

DITCH INSPECTION FORM

DITCH NAME Young Ditch

TYPE 6131

OVERALL RATING

RECONST DATE 1964

LAST EXC

5 EXCELLENT

0+00 STA 17 Bay

LENGTH 3000'

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$924.90

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	2.5'-3.0' +
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input checked="" type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	medium to heavy brush
FUTURE	2019	2020

This ditch starts at SR 53 east of Mulchay Road and flows generally south working it's way to Sandusky Bay. The original plan indicates some changes made to redirect the flow. Winous Point improved a channel to drain this ditch and others. Indicated elevations are 3.0' below the normal water levels. Water sits in this ditch for extended periods, and it is difficult to determine if it is backwater or trapped water. It is not practical to do any major work on this ditch unless it was repetitioned as a new project with a complete evaluation of project practicality.. In my opinion this project should go through the legal process to be removed from maintenance since the landowners are not receiving any benefits from the maintenance process.

DATE INSPECTED: 2.12.2018

INSPECTED BY:

M. Gargac