

DITCH INSPECTION FORM

DITCH NAME Zibble Ditch

TYPE 6131

OVERALL RATING

RECONST DATE 1961

LAST EXC 2008-2009

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA 2 Benton

LENGTH 7805'

ASSESSMENT BASE \$1604.42

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	Lowetr end sets with water most of the year
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE	2020 nothing planned	2021 nothing planned

Road ditch on the south side of SR 2 starting east of SR 590 and flowing east, crossing Lickert Harder Rd then crossing under SR 2 and flowing north through the Ottawa National Wildlife Refuge to the lake. Bottom excavation last done by ODOT. There is backwater influence at Lickert Harder and about 1/2 mile west, with standing water for othe extended periods, but once the water level drops the ditch flows pretty well. Due to this backwater it will sediment in rather fastr. This causes rapid cattail growth. Most maintenance done as routine by ODOT.

DATE INSPECTED: 1.11.2018

INSPECTED BY: Mike Gargac