DITCH INSPECTION FORM

TYPE SWCD Group

LAST FXC 1994

OVERALL RATING

5 EXCELLENT

 $\overline{\mathbb{M}}$ 4 GOOD

DITCH NAME Epling Ditch

RECONSTIDATE 1968

RECORDI BITTE 1000		LAGI LAG 100-	□ 3 FAIR
0+00 STA 5 Benton		LENGTH 14267'	
ASSESSMENT BASE \$8429.70			
CURRENT CONDITION AND PLAN OF ACTION			
SEDIMENT	☐ GOOD CONDITION ☐BOTTOM EXCAVATION 5-10 YRS ☑ NEEDS EXCAVATION SOON		2.0' at upper end downstream section 1.3-1.5' avg
BANK STABILITY	□ BANKS GOOD □ BANKS STEEP LESS THAN 1.5:1 □ RIP RAP NEEDED		Generally good some are steeper along the road section and nearer the outlet
OUTLET PIPES	GOOD CONDITION NEED REPAIR		
VEGETATION	☐GOOD CONTROL ☐ NEEDS MOWING ☐ BRUSH ☐ CATTAILS ☐ PHRAGMITIES		Light brush, some cattail and phragmitie growth along SR 2
FUTURE	2020		2021

Ditch starts at east side of Elliston Trowbridge Rd and flows east to Graytown Road, turns north along the west side of Graytown Rd, crossing SR 579 and then along the west side of SR 2 to the backwater marsh area of Crane Creek. The upper end 400'-600' has 2.0' average sediment due to the farming operations and runoff that comes from areas west of Elliston Trowbridge Rd. Some sections of this ditch have good filter strips, and some landowners farm over the edge. The lower reach along SR 2 is backwater influenced, and water can set for extended periods up to SR 579. Survey for exavation planned in 2017 was not completed. Currently staff is gathering data for the six year review and base increase hearing. Survey work is planned as soon as resources permit. Look to excavate in 2018 if possible.

DATE INSPECTED: 3.12.2018 INSPECTED BY: Mike Gargac