

DITCH INSPECTION FORM

DITCH NAME Millinger Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1967

LAST EXC 1991

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA 3 Benton

LENGTH 2372'

ASSESSMENT BASE \$767.10

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input checked="" type="checkbox"/> NEEDS EXCAVATION SOON	Excavation planned for spring 2018
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE	2020	2021

Entire ditch is on a 0.05% grade and it is backwater influenced from Turtle Creek with standing water for extended periods usually up to Walbridge Rd.. There is increased sediment at the upper end which is coming from a farm area that is not abutting the ditch. project under contract for a ditch bottom excavation spring 2018. At completion project will be rated good. No major work planned for 2019.

DATE INSPECTED: 2.23.2018

INSPECTED BY: Mike Gargac