

DITCH INSPECTION FORM

DITCH NAME Minier Ditch

TYPE 1515

OVERALL RATING

RECONST DATE 2008

LAST EXC

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA 36 Salem

LENGTH 5300'

ASSESSMENT BASE \$21734.60

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	BMowed in 2017 sonme light brush and cattails
FUTURE	2020	2021

Ditch starts at Brokate Road north of SR 163 and flows east to Carroll Erie Road, then turns south along the west side of Carroll Erie Rd crossing SR 163 to the backwater marsh area of the Portage River. Most of the section south of SR 163 was one sided construction with woods on the east side. This area usually needs every other year brush control to keep the brush from encroaching. Cattails and phragmites ara also a constant battle in this area. Brusdh spray and spot spray cattils and phragmities in 2019.

DATE INSPECTED: 2.15.2018

INSPECTED BY: Mike Gargac