

# DITCH INSPECTION FORM

DITCH NAME Schott Ditch #2

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1976

LAST EXC 2015

5 EXCELLENT

4 GOOD

0+00 STA 6 Harris

LENGTH 5727'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$9857.25

## CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Light brush
FUTURE	2020 nothing planned	2021

This ditch outlets into the Kempke Road Ditch which outlets into Lacarpe Creek Harmon. A bottom excavation was completed in 2015. Most of the ditch has decent filter strips and good grass cover. This ditch generally only requires a mowing or spot brush spray every 2-3 years. Spot spray for brush 2018. Nothing planned for 2019.

DATE INSPECTED: 3.21.2018

INSPECTED BY: Mike Gargac