

DITCH INSPECTION FORM

DITCH NAME Barshel Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1976

LAST EXC 2013

5 EXCELLENT

4 GOOD

0+00 STA 8 Benton

LENGTH 3423

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$2655.45

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input checked="" type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input checked="" type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	light spotty brush
FUTURE	2020	2021

Ditch starts on the north side of the N&W RR west of Graytown Road and flows north crossing Hausencomb Road and outlets into Turtle Creek west of Graytown Road. North of Hausencomb Rd is in good shape. Good SS with 40' wide CREP filter strips. South of Hausencomb Road does not have any filter strips. Landowner consistently oversprays herbicide. No major work planned for 2019.

DATE INSPECTED: 2.15.2018

INSPECTED BY: Mike Gargac