

DITCH INSPECTION FORM

DITCH NAME Elmwood Park Sewer

TYPE 6131

OVERALL RATING

RECONST DATE 1961

LAST EXC

5 EXCELLENT

4 GOOD

3 FAIR

2 POOR

1 VERY POOR

0+00 STA 28 Clay

LENGTH 7067

ASSESSMENT BASE \$35715.45

CURRENT CONDITION AND PLAN OF ACTION

| | | |
|----------------|---|----------------------|
| SEDIMENT | <input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON | |
| BANK STABILITY | <input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED | |
| OUTLET PIPES | <input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR | |
| VEGETATION | <input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES | |
| FUTURE | 2020 nothing planned | 2021 nothing planned |

A collection of tile installed for street drainage in the Elmwood Park subdivision with an outlet to Richards Ditch. No visible breakdowns or issues. Most of the tile and catch basins are small by today's drainage standards. Leaves and other debris can cause problems. The outlet is free, in good shape and has good flow. No work planned for 2019.

DATE INSPECTED: 3.21.2018

INSPECTED BY: Mike Gargac