

# DITCH INSPECTION FORM

DITCH NAME Mylander Joint County

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1980

LAST EXC 2010

5 EXCELLENT

4 GOOD

0+00 STA Sandusky County

LENGTH 5170'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$2573.74

## CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input checked="" type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE	2020 inspection nothing planned	2021 inspection, nothing planned

Ditch starts on the south side of Schnieder Rd in Sandusky County and flows east to Four Mile House Rd then north outletting into a sewer and Nine Mile Creek. Salem TWP usually mows road side. Section along Schneider Road is lacking in filter strips. No major work planned for 2019.

DATE INSPECTED: 2.23.2018

INSPECTED BY: Mike Gargac