

# DITCH INSPECTION FORM

DITCH NAME Schlegel Ditch

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1967

LAST EXC 1996, 2013

5 EXCELLENT

4 GOOD

0+00 STA 2 Harris

LENGTH 6891'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$1328.40

## CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input checked="" type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	cattail growth due to flat grade
FUTURE	2020	2021

Generally in good condition. Filter strips and good access on about 85% of the ditch length. Due to grade cattails continue to be a problem in some sections. Spot spray cattails in 2019 if needed.

DATE INSPECTED: 3.29.2018

INSPECTED BY: Mike Gargac