

# DITCH INSPECTION FORM

DITCH NAME Schultz Ditch Brokate Branch

TYPE 6131

OVERALL RATING

RECONST DATE 2016

LAST EXC 2016

0+00 STA 25 Carroll

LENGTH

ASSESSMENT BASE 44508.50

- 5 EXCELLENT
- 4 GOOD
- 3 FAIR
- 2 POOR
- 1 VERY POOR

## CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	Needs reseeded
FUTURE	2020	2021

A short ditch on the east side of Brokate Road south of the Schultz Ditch Main. This is a new ditch constructed to drain the subdivision on Bonnie Jean Drive. Check seeding and spot seed if necessary in 2019.

DATE INSPECTED: 2.6.2017

INSPECTED BY: Jarred Molesky, Mike Gargac