

DITCH INSPECTION FORM

DITCH NAME SR 590 Beck

TYPE SWCD Group

OVERALL RATING

RECONST DATE 1969

LAST EXC 2009, 2013

5 EXCELLENT

4 GOOD

0+00 STA 10 Harris

LENGTH 4086'

3 FAIR

2 POOR

1 VERY POOR

ASSESSMENT BASE \$2165.65

CURRENT CONDITION AND PLAN OF ACTION

SEDIMENT	<input checked="" type="checkbox"/> GOOD CONDITION <input type="checkbox"/> BOTTOM EXCAVATION 5-10 YRS <input type="checkbox"/> NEEDS EXCAVATION SOON	
BANK STABILITY	<input type="checkbox"/> BANKS GOOD <input type="checkbox"/> BANKS STEEP LESS THAN 1.5:1 <input type="checkbox"/> RIP RAP NEEDED	
OUTLET PIPES	<input type="checkbox"/> GOOD CONDITION <input type="checkbox"/> NEED REPAIR	
VEGETATION	<input type="checkbox"/> GOOD CONTROL <input type="checkbox"/> NEEDS MOWING <input type="checkbox"/> BRUSH <input type="checkbox"/> CATTAILS <input type="checkbox"/> PHRAGMITIES	
FUTURE	2020 nothing planned	2021

The original project was a road ditch on the west side of SR 590 just north of SR105. It flows from north to south and outlets into a sewer which crosses SR 105 and outlets into the Portage River. In 2013 ODOT piped and closed most of the ditch from north of SR 105 almost to the upper end. Very little work is needed. The upstream end is still an open ditch. No major work planned for 2019.

DATE INSPECTED: 2.1.2018

INSPECTED BY: Mike Gargac